

HBM 60 ZX Parts List

Ref #	Description	Qty Required	HBM 60 ZX Part #
1	Nose Piece HBM 60ZX	1	200445000
2	Eccentric Weight HBM 60ZX	1	200446000
3	Bearing 6304JR2LLHC3	2	401161000
4	Washer M20.5 x 30	2	301637000
5	Bolt M8 x 30	2	100400142
6	Rotor HBM 60ZX	1	301638000
7	Bearing 609zzC3	2	511606090
8	Retaining Ring S9	1	432100090
9	Motor Body (w/Stator) HBM 60 ZX	1	100711000
10	Hose Joint HBM 60 ZX	1	200054000
11	Lead Wire Guide	1	300006000
12	Lead Wire Guide (Cone)	1	300008000
13	Terminal Boot Cap	1	200038000
14	Lead Wire Guide (Rubber)	1	300161000
15	Sector Tube R6.5 x 3.5	3	300187000
16	Compression Ring M13 x 17	1	300010000
17	Hose Connector Extension	1	200061000
1--17	HBM 60ZX Head Assy Complete	1	100710000
18	Heat Shrink Tube	0	Obsolete
19	Inner Cord Guide	0	Obsolete
20	Heat Shrink Tube	0	Obsolete
21	Curl Cord 1.5m	1	301437000
22	Butt Splice Solder Sleeve	6	491614001
23	Ring Connector Solder Sleeve	3	491614002
24	Hose HMB-Z 21 x 36 (Per Foot)	1	338102136
25	Hose Band M38 W-14	3	470320380
28	Inner Wire Guide	1	310961231
29	HBM Switch Case Housing	1	300118100
30	Switch HBM (W/Fuse)	1	500158000
33	Screw M4 x 8 (Not Shown)	6	581000100
34	Screw M4 x 25	4	583504025
35	Switch Packing HBM	1	310661241
36	HBM-ZX Switch Case Cover	1	300182100
37	Switch Support Block	0	Obsolete
38	Rubber Ring M15 x 22	1	301643000
39	Compression Washer M15.5 x 22	1	310861231
40	Compression Nut M15.5	1	310461231
41	Sticker HBM	0	Obsolete
42	Bolt M5 x 20 SW SUS	4	585105020
43	Seal Ring HBM	1	310761240
44	Insulation Sheet	0	Obsolete
45	Cord Support Boot (HBM)	1	331861253
46	Clamp Band N46	1	570300460
47	Cord 12/3 (Per FT)	1	099991005
48	Ring Connector Solder Sleeve	6	491210001
49	Ring Connector	0	Same as 48
50a	EP-30 Plug (Standard)	1	100219100
50b	Twist-Loc Plug (Optional)	1	090101023
51	Serial Number Plate	1	Obsolete
52	Fuse Blade Type 30Amp	2	555200160
53	Teflon Sheet HBM	1	301751000
28--53	Power Cord Assy. (Plug Not Included)	1	341060152